

FAR 135.143 requires all new transponder installations to comply with TSO C-112 (Mode S). Since the FAA has not fielded the requisite ground equipment for Mode S, numerous exemptions have been granted allowing installation of new TSO C-74 transponders. The Mode S requirement should be removed from FAR 135, and installation of new TSO C-74 units routinely allowed.